

Release Notes

LCOS

10.92 Rel

Table of contents

03	1. Preface
03	2. The release tag in the software name
04	3. Device-specific compatibility to LCOS 10.92
04	LANCOM devices without support as of LCOS 10.92
04	4. Advices regarding LCOS 10.92
04	General notes on the update
04	Information on default settings
05	5. Feature overview LCOS 10.92
05	5.1 Feature highlights
05	Cloud-based network security with the LANCOM Security Essentials Option
06	6. History LCOS 10.92
06	LCOS improvements 10.92.0018 Rel
08	7. General advice
08	Disclaimer
08	Backing up the current configuration
08	Using converter firmwares to free up memory



1. Preface

The LANCOM family of operating systems—LCOS, LCOS SX, LCOS LX, and LCOS FX—forms the trusted basis for the entire LANCOM range of products. Within the scope of the hardware specified by the products, the latest firmware version is available for all LANCOM products and is offered by LANCOM Systems for download free of charge.

This document describes the innovations within LCOS software release 10.92 Rel, as well as the improvements since the previous version.

Before upgrading the firmware, please pay close attention to chapter 7 “General advice” of this document.

Latest support notes and known issues regarding the current LCOS version can be found in the support area of our website

www.lancom-systems.com/service-support/instant-help/common-support-tips

2. The release tag in the software name

Release Candidate (RC)

A Release Candidate has been extensively tested by LANCOM and includes new LCOS features. It is suitable for testing and is not recommended for use in productive environments.

Release Version (REL)

The release version has been extensively and successfully tested in practice. It contains new features and improvements over previous LANCOM operating system versions and is therefore recommended for use in productive environments.

Release Update (RU)

A release update is a further development of an initial release version in productive environments and contains minor improvements, security fixes, bug fixes and smaller features.

Security Update (SU)

Contains important security fixes for the respective LANCOM operating system version and ensures that your security level remains very high on an ongoing basis in your productive environment.



3. Device-specific compatibility to LCOS 10.92

LANCOM products regularly receive major firmware releases throughout their life-time which provide new features and bugfixes.

LCOS release updates including bugfixes and general improvements are available on a regular basis for devices which do not support the latest LCOS version. You can find an overview of the latest supported LCOS version for your device under www.lancom-systems.com/products/firmware/lifecycle-management/product-tables

LANCOM devices without support as of LCOS 10.92

- LANCOM R800V
- LANCOM LN-630acn
- LANCOM 1781VA
- LANCOM 1906VA-4G
- LANCOM L-322agn (R2)
- LANCOM LN-862
- LANCOM LN-860
- LANCOM OAP-830
- LANCOM OAP-1700B
- LANCOM OAP-821
- LANCOM OAP-822
- LANCOM IAP-1781VAW(+)

4. Advices regarding LCOS 10.92

General notes on the update

As of LCOS 10.90, the CLI menu for VRRP has been moved from '/Setup/IP-Router/VRRP/' to '/Setup/VRRP/'. The table structure and the associated OID path have also changed due to the support for VRRPv3 and IPv6.

Please note that add-ins for the LMC and any existing scripts for VRRP must be adapted for LCOS 10.90 and higher. Existing scripts for VRRP are not compatible with LCOS 10.90 and higher.

Information on default settings

Devices delivered with LCOS 10.00 or higher automatically connect to the LANCOM Management Cloud (LMC). This functionality provides zero-touch installation for new devices. In case you do not want to use the LMC, this feature can be disabled while running the default setup wizard for the initial configuration, or at any time from within LANconfig under Management > LMC. You can manually re-enable the usage of the LMC whenever you want.

5. Feature overview LCOS 10.92

5.1 Feature highlights

Cloud-based network security with the LANCOM Security Essentials Option

With LCOS 10.92, you fulfill all the requirements to upgrade your devices with the LANCOM Security Essentials Option. The LANCOM Security Essentials Option provides an efficient and reliable solution to protect networks against threats such as ransomware, phishing, malware, and credential theft. The integrated Content Filter effectively blocks unwanted and illegal internet content – preserving corporate integrity and significantly reducing liability risks. At the same time, the BPjM module of the German Federal Review Board for Media Harmful to Minors (BzKJ) reliably shields minors from harmful content. The underlying database used to verify website content is hosted in a GDPR-compliant cloud provided by European security specialist Bitdefender. For maximum scalability, use of the option is not limited to a specific number of users – making it ideal for growing networks.

Note: The LANCOM Security Essentials Option is available as an upgrade for LANCOM SD-WAN gateways, SD-WAN central site gateways, and WLAN controllers as the successor product to the LANCOM Content Filter.

You can find further features within the individual builds sections in chapter 6 “History LCOS 10.92”.

6. History LCOS 10.92

LCOS improvements 10.92.0018 Rel

New features

- Support for the LANCOM Security Essentials Option
- Change of the Content Filter to Bitdefender
Please note that some of the categories have changed and new categories have been added as a result of the change. It is recommended to check the configuration after the LCOS update. Please also refer to the [notes on the update](#).
- Support for the backup/restore function of the device
- Support for Dynamic RADIUS Caching
- The behavior for inter-tunnel traffic can be configured in L2TPv3.

Bug fixes

General

- When using an unmasked default route for an IKEv2 connection, it was incorrectly displayed that the DNS server could be reached from the WAN.
- The DSL line code has been updated to version 12.9.1.2.0.7 for devices of the 180xVA and 1926/1936 series.
- The password change of a logged-in TACACS user was acknowledged in WEBconfig with the error message "Not Found". As a result, the password change failed.
- When repeatedly reading out the console path 'Status/VDSL/Line-Type' (this also affected the higher-level path 'Status/VDSL') with the repeat command (e.g. "repeat 3 ls Status/VDSL/Line-Type"), the information was only output once.
- If no gateway was entered on the standby router in the DHCP network in a VRRP scenario (0.0.0.0), the standby router sent a DHCP offer without a gateway instead of using the VRRP IP address. If an end device first received the DHCP offer from the standby router instead of the master router, it did not accept the assigned IP address and communication was not possible.
- If the VLAN of a network - and thus also the routing tag of the network and the OSPF instance - was changed in an OSPF scenario, this resulted in the OSPF neighbor subsequently remaining in the 'down' status and the connection not being re-established.

VPN

- If a router with several active Internet connections and an IKEv2 connection with a specific routing tag received an IKE packet with the message type 'Redirect', the router changed the routing tag for the outgoing IKE_SA_INIT to 0 instead of retaining the previous routing tag. As a result, the VPN communication was then transmitted via the wrong Internet connection.

Wi-Fi

- The IAPP table can hold a maximum of 2048 entries. New access points can therefore no longer be added once the maximum has been reached.
If an access point could no longer be added to the IAPP table and therefore could not be found in the table, this led to an immediate restart of the access point.
- If there was an IP address entry for a freely accessible web server in the 'Setup/Public-Spot-Module/Free-Server' table, an error message was displayed when an HTML page of this web server was called up due to a missing HTML header.

VoIP

- If communication with a particular destination was only possible via a specific, dynamically learned route with 'next hop' (e.g. via BGP), but a statically configured default route without 'next hop' was also configured for the same remote station, but with a different routing tag, and the router received a packet for the destination network before the dynamic route was learned, the router did not replace the static route with the dynamic route for the session (the static route was not invalidated). As a result, the static route continued to be used and the destination network could not be reached via it.

7. General advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

Backing up the current configuration

Before upgrading your LANCOM devices to a new LCOS version it is essential to backup the configuration data!

Due to extensive features it is **not possible to downgrade** to a previous firmware without using the backup configuration.

If you want to upgrade devices which are only accessible via router connections or Wi-Fi bridges, please keep in mind to upgrade the remote device first and the local device afterwards. Please see the [LCOS reference manual](#) for instructions on how to upgrade the firmware.

We strongly recommend updating productive systems in client environment only after internal tests. Despite intense internal and external quality assurance procedures possibly not all risks can be eliminated by LANCOM Systems.

Using converter firmwares to free up memory

Due to numerous new functions within the LCOS firmware it may not be possible in some circumstances for older devices to keep two fully-featured firmware versions at the same time in the device. To gain more free memory, a smaller firmware with less functionality has to be uploaded to the device first. As a result, significantly more memory will be available for a second firmware.

This installation has to be done only once by using a “converter firmware”.

After having installed the converter firmware, the firmsafe function of the LANCOM device is only available on a limited scale. The update to a new firmware is furthermore possible without any problems.

However, after a failed update the LANCOM device works with the converter firmware which only allows local device access. Any advanced functionality, particularly the remote administration, is not available as long as the converter firmware is active.

